

## Taiwan Semiconductor Co., Ltd.

### Product Discontinuing Notification

<b>1. PDN No.:</b>	<i>QPDN08005</i>
<b>2. To:</b>	<i>Sales</i>
<b>3. Issued by:</b>	Ray Wu
<b>4. Issue date:</b>	2008/09/17
<b>5. Affected product/ product family:</b>	<b>6. Recommended replacement:</b>
See attached list: <i>QPDN08005.xls</i>	Please contact with TSC regional sales office for nearest replacement.
<b>7. Reason for discontinuing:</b>	
In order to improve production efficiency, the low demand products are decided discontinuous. The operation resource will transfer to other products.	
<b>8. Last time buy/ order entry:</b>	No longer production.
<b>9. Last shipment date:</b>	No longer production.
<b>10. Please let us know if you have any question/ comment:</b>	
<b>11. Customer feedback required latest: (should we receive no feedback, the change will be deemed as accepted!)</b>	2008/10/17
<b>12. Approved by:</b>	<b>L.C.Kao</b>

(your answer pls send to below mentioned address)

Ray Wu, Taiwan Semiconductor Co., Ltd. 11F. No. 205, Sec. 3, Beishin Rd., Shindian City, Taipei, Taiwan 231, R.O.C.

Tel: 886-2-8913-1588 Ext.2201, Fax: 886-2-8913-1788, E-mail: Ray Wu@mail.ts.com.tw